

BTM. CEILING JST.

FINISH FLOOR

EXISTING WOOD -

REINISH AS REQ'D

FRAMED STOREFRONT

WINDOW (TO REMAIN),

—12" STEEL 2X10 WD JSTS @ 12" O.C.


BEAM

→ 4"Ø STEEL COLUMN

STAINED CONCRETE FLOOR

2X10 WD JSTS @ 12" O.C.

EXISTING 1HR SEPARATION



LEGEND

NEW WALL: 2x4 WOOD STUDS @ 16"O.C. WITH

PIVOT BREWING - SATELLITE LOCATION INTERIOR RENOVATIONS 1753 BARDSTOWN ROAD - LOUISVILLE, KENTUCKY johnson • early • architects

43 SEAL EXTERIOR DOOR THRESHOLDS

44 REPAIR DAMAGED WOOD TRIM AT DOOR LATCH

DOORS. RESTAIN/RECOAT AS REQ'D TO MAKE LIKE NEW

131 prosperous place, suite 19b • lexington, kentucky 40509 phone: 859-259-1515 • fax: 859-231-5060 • e-mail: earlyjb@jearchitects.net

**GENERAL NOTES** 

SURROUNDING FLOOR.

FOR TENANT'S NEW FINISHES.

**(00) NEW WORK NOTES** 

PATCH & REPAIR ALL GWB AS REQ'D FOR NEW PAINT FINISH

REMOVE EXISTING FINISHES WHERE REQ'D. TO MAKE WAY

NEW PLUMBING FIXTURES. FLOOR TO BE PATCHED & REPAIRED AFTER INSTALLATION OF NEW FIXTURES. FLOOR

PATCHING SHOULD BE SMOOTHG & FLUSH WITH

SAW CUT EXISTING FLOORS AS REQ'D FOR INSTALLATION OF

**NEW PLAN & ELEVATIONS**